



Reverse Engineered from:
 Assy. No. 99P0073-000 Rev. J

Part Numbers Skipped
 CR10
 R11, 14, 15, 21
 C17, 28

Apple X/Lisa "DataPower" Power Supply			
2002-01-12	Sheet 1 of 2	Rev. B	Drawn by: JDM
		Checked by: TS	
Notes:			
1. There are NO 4-way connections on this diagram			
2. Leading slash indicates signal is active low			
3. Send corrections to: bugs@SigmaSevenSystems.com			
4. Use this drawing at your own risk			